

# DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt Governor Kathleen Clarke

**Executive Director** Lowell P. Braxton **Division Director** 

1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)



INSPECTION REPORT

Partial XXX	Complete	Expl	oration
Inspection Date:	08/07/2002/	Time:	9:00 -12:00
	e of Last Insn		

Mine Name: Star Point Mine	County: Carbon	Permit Number: <u>C/007/006</u>						
Permittee and/or Operator's Name: Plateau Mining Corporation								
Business Address: P.O. Box 30, Helper, Utah 84526								
Company Official(s): Johnny Pappas								
State Official(s): Karl R. Houskeeper	Federal Offi	cial(s):_None						
Weather Conditions: Clear, Temp 93°F								
Type of Mining Activity: Underground XXX Surface Prep PlantOther								
Existing Acreage: Permitted 9084 Disturbed	ed 213.4 Regraded	Seeded						
Status: Active Reclamation								

## REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		<b>EVALUATED</b>	N/A	COMMENTS	NOV/ENF	
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	ſ Ţ				
2.	SIGNS AND MARKERS	$\overline{[X]}$	ΞĪ	[X]	$\Box$	
3.	TOPSOIL		ΞĪ			
4.	HYDROLOGIC BALANCE:		-			
a.	DIVERSIONS	[X]	$\Box$	[X]		
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[X]			· [_]	
c.	OTHER SEDIMENT CONTROL MEASURES	[X]				
d.	WATER MONITORING	$\overline{[X]}$		[X]	$\Box$	
e.	EFFLUENT LIMITATIONS				. []	
5.	EXPLOSIVES		لَــاً			
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES		لَـا			
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	$\overline{[X]}$		[X]		
8.	NONCOAL WASTE	口	Ĺ			
9.	PROTECTION OF FISH, WILDLIFE AND RELATED					
	ENVIRONMENTAL ISSUES			· [_]		
10.	SLIDES AND OTHER DAMAGE					
11.	CONTEMPORANEOUS RECLAMATION					
12.	BACKFILLING AND GRADING					
13.	REVEGETATION	[_]				
14.	SUBSIDENCE CONTROL	Ĺĺ				
15.	CESSATION OF OPERATIONS					
16.	ROADS:					
a.	CONSTRUCTION/MAINTENANCE/SURFACING	. [_]				
b.	DRAINAGE CONTROLS					
17.	OTHER TRANSPORTATION FACILITIES					
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS					
19.	AVS CHECK (4 <sup>th</sup> Quarter- April, May, June)					
20.	AIR QUALITY PERMIT	. 🔲				
21.	BONDING & INSURANCE	Τ٦	[ ]	[ ]		

#### INSPECTION REPORT

(Continuation Sheet)

PERMIT NUMBER: <u>C/007/006</u>

DATE OF INSPECTION: 08/07/2002

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

#### 2. SIGNS AND MARKERS

The ID sign is located near the permit boundary within the disturbed area. The refuse pile signs are in place and contained the proper information. Other markers as required by the coal rules were in place.

# 4A. HYDROLOGIC BALANCE: DIVERSIONS

The construction of diversions on the reclaimed Lions Deck was in process during the inspection. A registered P.E. was on site to make sure that the diversions are constructed according to design.

Other diversions on site were inspected and were in good repair.

# 4D. HYDROLOGIC BALANCE: WATER MONITORING

Checked the EDI web site prior to the inspection. Water monitoring is current.

## 7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

Refuse material is being excavated and hauled to the Sunnyside Cogeneration Plant. Sunnyside Cogeneration Associates (SCA) owns the refuse pile and has an application in to the Division to permit the facility under their name. The current permit holder is Plateau Mining Corporation (PMC). Tonnage records are being maintained by PMC until the permit is received by SCA.

PMC is hauling refuse material from the old refuse pile that is being reclaimed and placing it adjacent to the toe of the new refuse pile. This material is being graded and compacted it as it is placed on the pile.

Inspector's Signature:

Karl R. Houskeeper

Date: August 7, 2002

Note:

This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc:

James Fulton, OSM Johnny Pappas, Plateau

Price Field office

O:\007006.STP\Compliance\2002\p 0807.doc